

FDM 211 Errata

Errata Date	Summary of Revisions
11/21/2017	Clarified language on limits of FC on paved shoulders where median barrier wall is continuous and shoulder slopes toward the travel lane in 211.4.3.
11/1/2017	Corrected a Table reference from Table 211.9.2 to Table 210.10.2 in 211.9.2.
11/22/2017	Corrected spelling error of "Sep <u>e</u> ration" in Exhibit 211-4 title. Also corrected spelling of "Ramp" in a bookmark.