

## FDM 215 Errata

Errata Date	Summary of Revisions
11/29/2017	Updated blue box to say Delete the last two sentences in 215.2.6.
11/29/2017	Added "and High Speed Curbed" to heading for "Flush Shoulder" column in Table 215.2.3 Roadside Slope Criteria.
11/9/2017	Corrected figure 215.4.5 for the critical bridge value.
2/6/2018	Corrected note (4) in the legend to read "521-001" from "521-002" in Figure 215.4.5.