

FDM 306 Errata

Errata Date	Summary of Revisions
12/7/2017	Removed "At the Contractor's Option" from the shoulder construction with optional base material note. Updated in standard notes (2) and (3) in 306.5, and also in Exhibits 306 -1, -2, -3, -7, and -8.